

	Type	L #	Hits	Search Text
10	BRS	L10	5388	(integrator or integrating) with resist\$4 with capacit\$8 with (amplifier or amplifying or amplification or op-amp or operational-amplifier or operational-amplifying or operational-amplification)
11	BRS	L11	1342	10 and ((integrator or integrating).ti. or (integrator or integrating).ab. or (integrator or integrating).clm.) and ((resist\$4 with capacit\$8 with (amplifier or amplifying or amplification or op-amp or operational-amplifier or operational-amplifying or operational-amplification)).ab. or (resist\$6 with capacit\$8 with (amplifier or amplifying or amplification or op-amp or operational-amplifier or operational-amplifying or operational-amplification)).clm.)
12	BRS	L12	357	11 and (resist\$4 with capacit\$8 with (series or serial\$4))